### **TECH TALK:** Top 4 Common Fluid System Problems and How to Avoid Them


01/21/2021



Swagelok Northwest (US)


## Meet Your Field Engineers

#### Adam Ghannoum Field Engineer



## Meet Your Field Engineers

#### Matt Hasenohr Field Engineer





## Agenda

- Data Collection
- Trend Review
  - Particulates and Filtration
  - Proper Handling of VCR Components
  - Hose Selection and Install
  - Elastomer Selection
- How Does This Help You?
- Questions

## **Data Collection**

#### How Did We Collect This Data?

- Each time a customer returns an item:
  - Item is evaluated locally
  - Item returned to Swagelok Factory
  - Report completed describing findings
  - Entered into internal database to store findings

#### **Data Analysis**

- After years of collection, we have been able to:
  - Parse data into recurring themes
  - Develop targeted training or education
  - Focus on reducing future returns or downtime



## **Trend Review**

#### **Overview**

- Particulates and Filtration
- Proper Handling of VCR Components
- Hose Selection and Installation
- Elastomer Selection

#### **Covered Content:**

- Review of Returned Items
- Signs and Symptoms
- Best Practices






## Filtration and Particulates - Review of Returned Products



### "The customer reports the regulator cannot hold a set pressure."




# Filtration and Particulates - Signs and Symptoms



## *"Foreign contamination on the seat sealing surface would not allow the regulator to create a full seal."*

### Inability to seal

- Particulates interrupting sealing surface
- Damage to sealing surface
- Common during start up
- Common in systems with high particulate load



## Filtration and Particulates - Best Practices

- **Use Filtration Upstream of Sensitive Equipment** 
  - Example: Regulators
- **Ensure filter element is suitable for particulate size**
- Removal of captured particulate if possible
  - Blowback








## Proper Handling of VCR Components - Review of Returned Products




### "The customer reported the valve failed their CDA leak test."



# VCR Handling and Installation - Signs and Symptoms



#### "Damage was observed on the VCR bead of the outlet port."



#### Commonly caused by:

- Visual Damage to Gland
- Mis-Handling During Install
- Mis-Handling Prior to Install


## VCR Handling and Installation - Best Practices



#### Precautions should be taken to protect the seal surface of the VCR end connections:

- Assembling caps when waiting for installation
- Proper Training to Align with Installation Procedure
- Use of New Gaskets during remake







## Hose Selection and Installation - Review of Returned Products



#### "The Hose Leaks"



# Hose Selection and Installation - Signs and Symptoms



## "Mechanical damage was likely caused by the stainless steel over braid puncturing the inner core tube."

#### Commonly caused by:

- Excessive bending during install
- Vibration
- Incorrect Length




## **Hose Selection and Installation - Best Practices**




#### **Clearly determine application details**

- Static vs Dynamic
- Media
- Temperature and Pressure
- Proper Working Length
- Bend Radius Requirement











## Elastomer Selection - Review of Returned Products




### "The customer reported CDA was leaking from the actuators."





"The leakage was caused by compression set of the O-rings in both actuators."



## **Elastomer Selection - Best Practices**



#### **Application Information:**

- Temperature
- Pressure
- Interaction with Media



#### **Example Specific:**

- System temperature is higher than the catalog rated temperature of 65°C.
- Consider using a valve with an actuator assembled with FKM O-rings.



## **How Does This Help You?**

Identifying areas of common failure allows us to address the root causes

#### **Results**:

- Decreased Downtime
- Decreased Maintenance Cost
- Improved System Design
- Improved System Confidence







## Get In Touch

Matt Hasenohr Field Engineer Email: <u>Matthew.Hasenohr@swagelok.com</u>

#### Adam Ghannoum

Field Engineer Email: <u>Adam.Ghannoum@swagelok.com</u>

**Ryan Enquist** Marketing Communications Specialist Email: <u>Ryan.Enquist@swagelok.com</u>



